La Maria Maria Maria La Maria Maria

Laboratory-Indianapolis PLANT

DATE July 28, 1954

cc: Mr. T. E. Reilly

TO: Ur. H. R. Horner

J. A. Lauck

ST. LOUIS PARK PLANT INSPECTION

SUBJECT:



I) The most serious problem at the St. Louis Park plant is the boiler system and the plant water system which feeds the boiler. The water system must be improved soon or we can expect serious boiler damage. At present water is taken from a 12° well by an air lift, collected in an open pan about 3° x 4° x 6° and run off into an open pond. The pond usually has an oil slick and the water is not clear. A steam reciprocating pump is used to supply a 4° sorewed main with water from the pond. This main runs through the plant serving one plant washroom, the refinery, the office washroom, and the boiler house. A sample of this water taken from the office wash basin contained solid material both lighter and heavier than the water. It is this water which is used in the boiler and which must account for the poor condition of the Riley boiler. The boiler was turbined in May and already has accumulated up to 1/16° scale on the tubes and 1/8° on the shell. The boiler is normally shut down every three months for washing out.

The water taken directly from the well was tested by the state and was found to be safe water for drinking. However, without a closed water system it cannot be safe.

The air lift is supplied by a 35 HP air compressor which in addition furnishes air intermittently for loading tar trucks. But for water service the compressor must run almost constantly. In addition to the compressor a steam oump must run constantly on water service.

to:	·	
•	•	

FROM:_____

SUBJECT:_____

The air lift might be blamed for the corrosion of the 4" screwed water line through the plant. This line has approximately 32 wooden plugs driven into it through the years as leaks developed. Without water meters we cannot tell how much water is lost between the pump and the boiler house but it probably is appreciable.

No standby connection to the city water main in installed.

The boiler feedwater pumps are in bad condition and both must be used to supply water to one boiler. I am sure these pumps are beyond economic repair.

The boiler feedwater heater does a good job in spite of its age and improper installation. The heater is too low to provide proper suction head to the feedwater pumps. Raising the heater 4'-6" will provide that head and will not interfere with overhead equipment. At the time the heater is moved an exhaust steam header should be added to allow a sufficient straight run of pipe before the oil separating section of the heater. The oil separator cannot function properly without this straight section and the oil deposits in the heater are enough evidence of poor operation.

I believe the time has come to change to gas fuel in the boiler. A copy of the gas rate in effect is included in my first report on the St. Louis Park plant. A comparison will be made with the present oil costs before proceeding further on this conversion but many of the Minneapolis industries have already changed to gas, and several burner peddlers have already promised us great savings in fuel costs by converting to gas. The gas is

_	•	~	=	

DATE
το,
FROM:
6UBJECT:
available only on an interruptible service and therefore oil must be main-
tained as standby.
The oil burners in the Riley boiler operate at 250 psi. We reduced
the pressure to about 200 psi and the fires went out. After a few minor
flarebacks we left the oil pressure at 250 psi.
No flame failure protection, low water cutoff, feedwater regulator
or combustion control is installed. Two steam flow meters are installed b
both have been inoperable for several years.
The boiler refractory has failed in several places so that the steel
casing has burned through. The casing was repaired but the refractory
repairs, if made at all, were not satisfactory. Many cracks remain and
many sections of brick have fallen out. The boiler top is likewise in poo
shape and moves considerably during operation as if the refractory were
broken or loose.
These conditions are being described by letter to the Riley Stoker
Corp. by the plant engineer, Er. John Peters, who is asking advice in re-
pairing the boiler top. The side walls will be patched at the next shut-
down, according to Mr. Peters.
My recommendation for the boiler plant is that we make improvements
in the following order:
Treating 1) Provide an electric deep well pump and a pressure tank for
the 12" well. the total meter
Ayun Amunic 2) Install a new plant water main from the well to the boiler

,	' ,PLANT
į	DATE
	TO:
	FROM:
	house with additional connections as at present
	Highin de uneatric
1	Install a connection with meter from the city water firemain
•	in the plant to the boiler house for standby service.
ን	4) Provide two new boiler feedwater pumps—one steam turbine
•	and one electric.
7	control , county 5) Raise the feedwater heater and install a proper exhaust steam
	header.
P	astility in the B) Install feedwater regulator, low water cutoff and flame failur
	protection in the Riley Boiler.
2	a marine
•	المرابع 7) Install a gas main into the plant for use first at the boiler
_	house and later in the refinery.
ند	(and we will all new oil burners which operate at 50 psi in the boiler
	for standby and gas burners for regular service.
	Emmis believe 9) Install combustion controls on the boiler and repair or replace
	one flow meter.
W.	Jun abanda and 10) Investigate the practicability of burning wood shavings in
,-	the Riley boiler along with its regular fuel.
•	The 12" well is over 900 ft. deep and contains a 12" casing of unknown
	length, 152 ft. of 4 1/2" pipe and 141 ft. of 1 1/2" pipe. Water level is
	approximately 40 ft. below the ground.
	If the electric well pump is provided, the pond will dry up and the
	fire pump will have to be connected to the city water firemain in the plant.
	At present it takes suction only from the pond. Evaporation is too great to
	201155

S . TT		
	TE	~ •

ro:		
•		
PROM:	 ·	
_	•	

keep the pond for a fire water reservoir.

II) The next problem of importance is the condtion of the condensers and pans in the refinery and the vapor system outside the building.

The condensers and pans are badly deteriorated. The condenser coils are not complete since they were replaced on the job and it was impossible to fit all langths of pipe into the condenser as originally designed. As a result, the oils are too hot and excessive vapors accumulate. These vapors are drawn into a large tank on the refinery roof by a 20 HP fan and ejected through another large tank on the ground outside the refinery and through a water scrubber. In spite of this Rube Goldberg the fumes cause complaints from the neighbors. A new housing project is located to the southeast, in the direction of the prevailing winds, and on a hill so that they are on a level with our stacks.

If these condensers and pans were replaced, and condenser coils of proper length were used, the amount of vapors might be handled by standard stacks. If the fumes are still objectionable, then I suggest using an old condenser and a small steam jet to draw the fumes in. This system is used at Lone Star for pitch fumes while blowing stills and it completely eliminates the fumes. If non-condensable gases remaining are objectionable, they might be burned in a small unit as described in an article entitled control of Non-condensable Vapors, presented by Mr. Schulz of Flintkote Co. to the Asphalt Roofing Industry Bureau meeting of manufacturing executives. This article was sent you by Dr. Mootz on December 22, 1953. The equipment was

PLANT
DATE
•
in New Jersey. I will in-
L
the proposed pitch bays in the
shows the bays in the north-
•
tion, but the southeast end
four partial settings with
the southeast end so that the
room will not have to be re-
building for one-half the
to the centerline of the
om the southeast end of the
enterline is required so the
building or the track will
sightened out. The latter
when the coke pile is elimin-
ion of a covered losding dock.
efinery the track will have

produced by the Allied Asphalt and Mineral Co. vestigate this further during my trip to Newark III) Pitch Bays in Refinery-The small preliminary drawing of t refinery dated 6/17/54 is incorrect in that it west section. The usable stills ap in that sec contains four abandoned stills in settings and stills removed. There is sufficient space in t partition wall between the pan room and still r moved. The railroad track parallels the refinery length of the building at a distance of 10 ft. track. Then it curves outward and is 16'-6" fr building. A clearance of 8 ft. to the track ce loading dock will either have to be within the have to be moved away from the building and atr will be simple and the space will be available ated. It will, however, require the construct If the loading dook is to be built within the r to be straightened out to bring it close to the dock. The pan room in the southeast end contains 11 pans, 8 condensers, and a large amount of piping. This room, if cleared, might be used to house the water pressure tank mentioned in item I of this report, and the controls for

	- OF that it
•	Juggette for that it and got the live (
TO:	. The war of year of our
PROM:	multiple of the formal of the
ėtin įrot.	which we we wrong the system gain
the deep well pump.	fund of the trumber and of the
	Aso will the war
IV) The steam main through th	e tank farm consists of a 2" uninsulated
pipe running in trenches and is part	ly submerged in water. An overhead in-
sulated line will reduce the boiler	load considerably. The length of such
an insulated line will be approximat	ely 400 ft. but only the first 90 ft. of
this line need be overhead to clear	the roadway. The remainder should be
supported on piers near the ground f	or ease of maintenance.
V) The railroad tracks requir	re a large amount of repair work as out-
lined in my report on the plant. En	. Flaa has discovered a good deal on
frogs and switches with one of the r	eailroads in Minneapolis. They are aban-
doning a section of their railroad a	end are offering frogs and switches, many
of them new, at the price of sorap.	I advised Mr. Flaa and Mr. Holstrom to
purchase immediately all sections ne	eded to put our tradks in good condition
and enough for spare. The plant wel	der has been repairing tracks continuousl
but theamount of track makes it impo	essible for him to keep up with repairs
needed and perform other maintenance	jobs also.
	Very truly yours,
	Of to 1
JAL: rr	J. A. Lauck
After hard rains the wat	in The year and referring
- builling stands occurat a	
, , , , , , , , , , , , , , , , , , , ,	uns lown from The street to
to the contract of the contrac	201158 Am
•	201158 Am